## INFORMATION REPORT INFORMATION REPORT

this material contains information affecting CENTRAL UNITELLIGENOES AGENOM the meaning of the Espicinage Laws, Title 18, 11, 5, C. Socs. 793 and 794 the transmission or revelation of which in any manner to an unauthorized person is probibited by law.

13 SEP		C-O-N-F-I-D-E-N-T-I-A-L				
COUNTRY	Nigeria			REPORT NO.		
UBJECT	Niger River		•	DATE DISTR.	15 September 1967	25)
	Hydroelectric	c Project		NO. PAGES	3	25)
		•	•	REFERENCES		
ATE OF INFO.	11 August 19	67			•	
ACE & DATE ACQ					AREA INDEXED	
	TI	IIS IS UNEVĀL	UATED INFOR/	<u> </u>	•	
OURCE -					•	•
electr citing	the CIA number	ies of the pirs listed.	hotog <b>r</b> aphs o	described be	River Dam and Hydro- low may be obtained by	7
120461		background. being built	New Bussa to house th will be flo	is an extended is an extended out by	Niger River in the sive housing project n of the old town of the new lake when	•
1204617	•	Aerial view	of New Buss	a showing c	lose-up of new mosque.	ı
1204618	3	side. Form	er Kainji Is	sland is in t	from upstream (lake) the center with right	
			er River flo		right foreground and eft channel and throug	;h
1204619		all the Nige spillway in Aerial view Trees on the yet been cut	er River flo dam. of Niger Da e former Kai e, but the w	owing down le um looking do nji Island i	eft channel and througous ownstream (Southeast). In foreground have not Ill eventually be clea	•
1204619 1204620	. •	all the Nigo spillway in Aerial view Trees on the yet been cut ed to form to Aerial view bank the lei built up to right bank t	of Niger Da former Kai t, but the w the bottom o  of Niger Da ft rock-fill connect wit the right ro photograph	owing down loam looking do nji Island i shole area wing f the new Kam looking do wing wall oh cement cerck-fill wing but has not	ownstream (Southeast). In foreground have not ill eventually be clea	ir-

U C-O-N-F-I-D-E-N-T-I-A-L

25X1

25X1

Essinged (18th delicated and designation of the contraction of the con




The dissemination of this document is limited to civilian employees and active duty military personnel within the intelligence components of the USIB member agencies, and to those senior officials of the member agencies who must act upon the information. However, unless specifically confolled in accordance with paragraph 8 of DCID 1/7, it may be released to those components of the departments and agencies of the U. S. Government diffectly participating in the production of National Intelligence. IT SHALL NOT BE DISSEMINATED TO CONTRACTORS. It shall not be disseminated to organizations or personnel, including consultants, under a contractual relationship to the U. S. Government without the written permission of the originator.

25X1

- 1204622 Niger Dam looking downstream. Cement center section completed except for installation of spillway gates and intake gate for penstocks. Openings for penstocks leading to turbines clearly visible at bottom of cement center portion; two penstocks serve each turbine and generator. Eventual installation will be twelve turbine-generator sets: eight discharging into left channel and four into right channel. Right end of cement section is not yet connected to right rock-fill wing wall, since work is still in progress in dammed-off right channel of Niger River. Breakwater in the river below the dam is almost completed to provide protected entrance to lower navigation lock.
- 1204623- Aerial view of upper locks looking upstream (Northwest). The left rock-fill wing wall shows at the left of the photograph. The excavation in the foreground is passing basin for barges and other river vessels.
- 1204624 Aerial view of the Niger Dam looking upstream (Northwest). The entire current of the Niger River is passing through the spill-way at the right front of the photograph. At right of the photograph, is the left rock-fill wing wall connected to cement center portion but not yet built up to full height. New permanent bridge over the Niger shows in the left foreground. Right rock-fill wing wall mostly completed beyond bridge, but not yet connected to cement center portion.
- Close-up aerial view of the Niger Dam looking upstream. Outline 1204625 of former Kainji Island is clearly visible with entire Niger flowing through left channel and spillway which is at the right of the photograph. Dammed off right channel of the Niger shows at the left with upstream cofferdam in the upper left of the photograph. Cement center section of the dam completed, with power house for four initial generators almost completed halfway across the dam face. This part of the power house will contain two turbine-generators discharging into the left channel, two more discharging into the right channel and two sets of penstocks whose turbine will also discharge into the right channel of the Niger when installed later. The rest of the power house across the remaining portion of the dam face is not under construction at this time. It will cover the final six turbinegenerators for which penstocks are already built into the dam.
- 1204626 Oblique aerial view of the concrete center section of the Niger Dam looking upstream showing the almost completed portion of the power house, administration building in front of it and work in progress preparing the tailrace for the four turbine-generator sets which will eventually discharge into the right channel of the Niger (center foreground).
- Enfilade view of Niger Dam showing successively from foreground:
  work in progress in bed of dammed-off right channel of the Niger
  River; tailrace being prepared to discharge into right channel;
  concrete center section with power house and administrative
  building; left channel flowing through spillway with new permanent bridge spanning it at right of photograph; left rockfill wing wall almost completed back to upper lock in midground.

5 4



- 1204629 Aerial view of the fishhook bend in the Niger River at Awuru looking upstream. The navigation canal being constructed across the neck of the bend on the right bank does not show, but its downstream entrance is just outside the left edge of the photograph and the canal will run roughly parallel to the small highwater season channel shown in the photo cutting across the neck.
- 1204630 Aerial view of the navigation canal by-passing Awuru Rapids. Downstram entrance to the canal is in the foreground, lock is in the center and the upstream entrance is in the far background.
- 1204631 Aerial view of the lock being built in Awuru Rapids by-pass canal. The Niger River is shown in the background flowing down to the fishhook bend just outside the upper right corner of the photograph. The ends of the lock have been finished and gates installed but the sides not yet begun.
- 1204632 Aerial view of the lock in Awuru Rapids by-pass canal showing the Niger River below the fishhook bend flowing towards the lower end of the canal just outside the lower right corner of the photograph.
- 1204633 The upper entrance to the Awuru Rapids by-pass canal showing the weir across the river partially over-topped by the Niger River at flood season.
- 1204634 The excavated pit in which the lower navigation lock is being constructed, looking upstream.
- 1204635 Juncture of the future tailrace and dammed-off right channel of the Niger River showing the cement center section of the dam and the partially completed power house and the administration building. The large square gantry crane on top of the dam will travel back and forth and be used to open and close intake gates for penstocks. The drag lines on top of the dam at both ends are being used for construction purposes and will be removed upon completion of the dam.
- 1204636 Close-up of the power house entrance and the partially completed administration building with central concrete section of the Niger Dam looming over the top of the power house.

  Actual size of the dam can be judged by the people standing on the top.
- 1204637 Close-up of the downstream face of the Niger Dam showing from right to left: the left rock-fill wing wall of the dam being built on to the cement center portion; the framework of the spillway, gates to which are not yet installed; the discharge openings for the turbine-generator sets showing at the bottom of the foundations for future part of the power house to be built at a later date. The large square gantry crane for raising and lowering intake gates has been installed on the top of the dam (center).

25X1
1
1

Next 4 Page(s) In Document Exempt

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c. Power house & admin. bldg. 11 August 1967.

Confidential (17,29) CIA 1204636



NIGER DAM, NIGERIA, AUGUST 11, 1967.

Close up of power house entrance and partially completed administration builded 2004/05/261 CARRINGAS-04546A002309040Q07n0 of Niger Dam looming over top of power house. Actual size of dam can be judged by people standing on top.

NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E

New town of New Bussa u/c to house population of old Bussa which will be flooded by Niger Dam lake. 11 August 1967.

Confidential (6,7,10) CIA 1204616



NIGER DAM, NIGERIA, AUGUST 11, 1967.


1. View of New Bussa from the air with Niger River in backgrapproved Fewrelessa 2004/03/22enc Par BDR78-94546A9933000409071Ag built
to house population of Bussa, ancient town which will be
flooded out by new lake when Niger Dam is finished.

**STAT** 

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam u/c 1kg from upstream (lake) side. 11 August 1967.

Confidential (17,29) CIA 1204618



STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.

Aerial view of Niger Dam at Kainji from upstream (lake) side.

Former Kainji Island in center with right channel of Niger


Approved For Release 2004/05/26e Cha RDP 78:04546A003300010007-0 River flowing

10wn left channel and through spillway in dam.

NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E

New Bussa. Mosque center. 11 August 1967.

Confidential (6,7,10) CIA 1204617



Approved For Release 2004/03/26: CIA-RDP78-04546A00330001000770 11, 1967.

NIGER DAM, NIGERIA, AUGUST 11, 1967.

NIGER DAM, State of New Bussa showing close-up of New Mosque.

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c 1kg downstream. 11 August 1967.
Confidential (17,29)

CTA 1204621




STAT

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c 1kg downstream. 11 August 1967.
Confidential (17,29) CTA 1204620

25X1

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0



STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.

5. Aerial view of Niger Dam looking downstream. On left bank left rock-fill wing wall of dam has been built up to Approved For Release 2004/03/26; CJA-RDP78-04546A003860049607-9ight rock-fill wing wall shows on right of picture but has not yet been connected to cement center section

NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c 1kg SE downstream. 11 August 1967. 67. Confidential (17,29)

CTA 1207.610



**STAT** 

NIGER DAM, NIGERIA, AUGUST 11, 1967.

4. Aerial view of Niger Dam looking downstream (Southeast).

Trees on form Belegge 2004/03/26 nGIA+RDP 38-04540A00380004000/L0yet been cut but whole area will eventually be cleared to form bottom of new Kainji Lake.

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0 NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c 1kg downstream. 11 August 1967. Confidential (17,29)



STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.

7. Closer view of Niger Dam, looking downstream. Cement center section completed except for installation of spill-way gates, intake gates for penstocks. Openings for penstocks leading to turbines clearly visible at bottom of cement center portion, two penstocks serve each turbine and generator. Eventual installation will be 12 turbine—generator sets: 8 discharging into left channel and 4 into right channel. Right end of cement section not yet connected to right rock-fill wing wall, since work still in programmed for procedure of the programmed of the programmed of the programmed of the procedure of the procedur

25X1

NIGERIA WAC 783C KAINJI 09 50N 04 37E Niger River Dam u/c. Upper locks 1kg NW upstream. 11 August 1967.

Confidential

(17,29)

CIA 1204623



NIGER DAM, NIGERIA,

AUGUST 11, 1967

8. Aerial view of upper locks looking upstream (Northwest). Left rockfill wing wall shows at left of Approved For Release 2004/03/26 CIO-RDP 8:04546A003300010007-0 is passing basin for barges and


other river vessels.

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam u/c 1kg NW upstream. 11 Aug 1967.

Confidential (17,29) CIA 1204624

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0




NIGER DAM, NIGERIA, AUGUST 11, 1967.

Aerial view of Niger Dam looking upstream (Northwest).

Entire current of Niger River passing through spillway at right front of picture. At right of picture left rock-fill wing wall connected to cement center portion but not yet built up to full height. New permanent bridge Niger shapproved Ferrelease 2004/03/26: Right rock-fill wing wall mostly completed beyond bridge, but not yet connected to cement center portion.

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0 NIGERIA WAC 783C KAINJI 09 50N 04 37E 25X1 Niger River Dam u/c 1kg upstream. 11 Aug 1967. (17,29)Confidential CIA 1204625



10.

Close-up aerial view of Niger Dam looking upstream. line of former Kainji Island clearly wisible with entire Niger flowing through left channel and spillway which at right of picture. Dammed off right channel of Niger shows at left with upstream cofferdam in upper left of picture. Cement center section of dam completed, with power house for four initial generators almost completed halfway across This part of power house will contain two turbine-generators discharging into left channel, two more discharging into right channel and two sets of penstocks whose turbines will also discharge into right channel of Niger when installed later. Hest of power house across Approved Ferresease 2004603/261eCRIRDP78-04546A003300010007-0 which penstocks already built into dam.


NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c 1kg upstream at almost completed portion of power house. 11 August 1967.
Confidential (17,29) CIA 1204626



NIGERIA WAC 783C KAINJI 09 50N 04 <u>37E</u> Niger River Dam u/c. 11 August 1967.
Confidential (17,29)
CIA 1204627



NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E
Lkg NW upstream at Awuru Rapids in Niger River 11mi. below Niger Dam u/c.
11 August 1967.
Confidential (1,17,29) CIA 1204628 25X1



Aerial view looking upstream (Northwest) showing Awuru
Rapids in Niger River 11 miles below Niger Dam at Kainji.
Rapids in Niger River 11 miles below Niger Dam at Kainji.
These rapids will be by-passed by a short navigation canal
These rapids will be by-passed by a short navigation canal
across neck of sharp fishhook bend on far (right) bank.

across neck of sharp fishhook bend on far (right) bank.

Weir to divert water into upstream entrance of canal shows
acrossoved for Redease 2004/03/26: CIA-RDP78-04546A003300010007-0

NIGERIA WAC 783C KAINJI (NR) 09 50N 04 37E
Fishhook bend in Niger River at Awuru 1kg upstream near Niger Dam u/c.
11 August 1967.
Confidential (1,17,29) CIA 1204629



STAT

NIGER DAM, NIGERIA, AUGUST 11, 1967.

Aerial view of fishhook bend in Niger River at Awuru looking upstream. Navigation canal being constructed across neck of bend on right bank does not show, but its downstream entrance bend on right bank does not show, but its downstream entrance is just outside left edge of picture and canal will run is just outside left edge of picture season channel shown in roughly paragraphic across neck ppr78-04546A003300010007-0 this picture cutting across neck ppr78-04546A003300010007-0

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam Navigation canal by-passing Awuru Rapids. 11 Aug 1967.

Confidential (17,29)

CIA 1204630



STAT 15.

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam Project. Lock in Awuru Rapids by-pass canal u/c. 11 Aug
1967.
Confidential (17,29)
CIA 1204631



**STAT** 

16.

NIGER DAM, NIGERIA, AUGUST 11, 1967.

Aerial view of lock being built in Awuru Rapids by-pass canal. Niger River shown in background flowing down to fApproved For Release 2004/03/26 CIA POP 78:04546A0033090 10007 ic ture. Unds of lock have been finished and gates installed but sides not yet begun.

25X1

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c. Lock in Awuru Rapids by-pass canal. 11 Aug 1967.

Confidential (17,29) CIA 1204632



Approved for Release 2004/03/26: REARIN 78904946A009300010009-01 ng
Aerial view of 100K 2004/03/26: REARIN 78904946A009300010009-01 ng
Niger River below fishhook bend flowing towards lower end
Niger River below fishhook bend flowing towards lower end
Niger River below fishhook bend flowing towards lower end

**STAT** 

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c. Upper entrance to Awuru Rapids by-pass canal.
11 August 1967.
Confidential (17,29) CIA 120 CIA 1204633



STAT


NIGER DAM, NIGERIA, AUGUST 11, 1967.

18. Upper entrance to Awuru Rapids by-pass canal showing weir a approxed for Relaast 2014/93/26 a 614-Approx-04546Agg3300010097-0t flood

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam. Excavated pit in which lower navigation lock is u/c
lkg upstream. 11 August 1967.

(17)

CIA 1204634



**STAT** 

21.

Approved For Release 2004/03/26 ECIA RDP7% 94546A003300010007-0 View of excavated pit in which lower navigation lock being constructed, looking upstream.

NIGERIA WAC 783C KAINJI 09 50N 04 37E

Niger River Dam u/c. 11 August 1967.

Confidential (17,29)

CIA 1204635



STAT


22.

Juncture of future tailrace and dammed off right channel of Niger River showing cement center section of dam and of Niger River showing cement center section of dam and partially completed power house and administration building. Large square gantry crane on top of dam will travel ing. Large square gantry crane on top of dam at late gates back and forth and be used to open and close intake gates back and forth and be used to open and close intake gates for Approved For Release 2004/03/26n: GMARDPFS-04546A003300010007-0 upon completion of dam.

NIGERIA WAC 783C KAINJI 09 50N 04 37E
Niger River Dam u/c. Downstream face of dam. 11 August 1967.

Contidential (17,29) CIA 1204637

Approved For Release 2004/03/26 : CIA-RDP78-04546A003300010007-0



**STAT** 

24.

NIGER DAM, NIGERIA, AUGUST 11, 1967.

Close-up of downstream face of Niger Dam showing from right to left: left rock-fill wind wall of dam being built on to cement center portion; framework of spillway, gates to which not yet installed; discharge openings for turbine-generator sets showing at bottom of foundations for Turure parties as showing at bottom of foundations for Turure parties power noise Large square gantry crane for raising and lowering intake rates has been installed on top of dam (center).